


Errata

Page 541 (Volume 2)

Paper ID: 3,031 (Schipper, Golub)

Figure 2. Legend is missing. Correct figure below:



Page 699 (Volume 2)

Paper ID:4,063 (Gudbjerg, Persson)

Right-hand column: Third full paragraph:

"...energy audits carried out by the Norwegian regional energy centres."

To be replaced by:

"...energy audits carried out by the Norwegian Institute for Energy Technology (IFE)."

Page 833 (Volume 2)

Paper ID: 4,180 (Jakob, Nutter)

Table 1 to be replaced by the below table:

Insulation thickness (cm)	U-value (W/m ² K)	Investment costs (CHF/m ²)		Gross average costs (CHF/kWh _{UE})		
		Mean	Best practice	Compared to Ref. ER		Compared to Ref. M
				Mean	Best practice	Mean
0 (Ref. M)	0.85 - 1.1	35	35	N/A	N/A	-
12 (Ref. ER)	0.28	117	112	-	-	0.061
16	0.23	127	119	0.12	0.08	0.065
20	0.20	140	133	0.17	0.10	0.070
30	0.15	174	143	0.25	0.13	0.084

Ref. M = Reference maintenance (plaster repairs, façade coating)
 Ref. ER= Reference energetic refurbishment (12 cm external insulation)
 N/A = non-applicable

Note:

Papers 3,031 and 4,180 have been updated as pdf:s on the eceee web site, available for eceee members. (www.eceee.org, see "library+links" > "proceedings").